

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 8

999 18TH STREET- SUITE 300 DENVER, CO 80202-2466 Phone 800-227-8917 http://www.epa.gov/region08



Ref: 8EPR-SR

October 12, 2006

Water Quality Initiative, Attn: Stacey Ericksen City of Denver, OED, DH&ND 201 W Colfax, Dept 204 Denver, CO 80202

RE: 4601 Claude Ct

Dear Owner,

As part of the VB/I-70 Superfund Site investigation, we recently took soil samples at your property to find out if there is too much lead or arsenic in your yard. *The results show that your property does not require a cleanup.* The levels of both lead and arsenic are below our cleanup levels. The soil sampling results for your property are as follows:

ADDRESS: «Address»	EPA Cleanup Levels
Lead	
140 parts per million (ppm)	above 400 ppm
Arsenic	
6 ppm	above 70 ppm

This means that your property is not considered by EPA to be part of the VB/I-70 Superfund Site. EPA does not believe that further measures are necessary. You and your family are not at significant risk from arsenic through ordinary contact with soil in your yard while playing, working, gardening, etc. Please note that there may be small areas in your yard, particularly near your house, that may have higher levels of lead due to peeling, external lead-based paint. EPA encourages all owners of older properties to take reasonable precautions regarding lead-based paint.

For further information, please feel free to contact EPA Community Involvement Coordinators Jennifer Chergo at (303) 312-6601 or Patricia Courtney at (303) 312-6631.

Sincerely,

Victor Ketellapper

Remedial Project Manager

The Environmental Protection Agency, Region 8

4601 Claude Court Apprx.


	section	glids	flags
• •	J	28	2
], 5'	2	107	19
	3	 36 <i>ורו</i>	19 6 30= 5.7

VB - 4601 - CC - 01

VB-4661 - C€-02

VB-4601-CC-03

+1 huse 1120 1130 1135



NV 8/5/06 Id 7045

Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: VB-4601-CC-01 Client Project ID: 213001.01 Date Collected: 8/5/06

8/7/06

Date Received:

Lab Work Order: 06-5092 Lab Sample ID: 06-5092-07

Sample Matrix:

Soil

METALS

Method: SW6010 Prep Method: SW3050

Date Prepared: 8/8/06 Lab File ID: 080906PRE Dilution Factor:

Date Analyzed: 8/9/06 Method Blank: MB-10565 Lab Fraction ID: 06-5092-07A

Analytes **CAS Number** Result LQL Units Arsenic 7440-38-2 5.6 3.6 mg/Kg 150 5.3 Lead 7439-92-1 mg/Kg

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Approved

Definitions: NA - Not Applicable

LOL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 8/10/06

Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: VB-4601-CC-02

8/7/06

Client Project ID: 213001.01 Date Collected: 8/5/06

Date Received:

Lab Sample ID:

Lab Work Order: 06-5092 06-5092-08

Sample Matrix:

Soil

METALS

Prep Method: SW3050 Method: SW6010

Date Prepared: 8/8/06 Lab File ID: 080906PRE **Dilution Factor:**

Method Blank: MB-10565 Date Analyzed: 8/9/06 Lab Fraction ID: 06-5092-08A

Analytes **CAS Number** Result LQL Units 7440-38-2 5.7 3.9 Arsenic mg/Kg 7439-92-1 140 5.7 mg/Kg Lead

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Approved

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 8/10/06

Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: VB-4601-CC-03

Client Project ID: 213001.01 Date Collected: 8/5/06

Date Received:

8/7/06

Lab Work Order: 06-5092

06-5092-09

Lab Sample ID: Sample Matrix:

Soil

METALS

Method: SW6010

Date Prepared: 8/8/06 Lab File ID:

080906PRE

Dilution Factor:

Prep Method: SW3050

Lab Fraction ID: 06-5092-09A

Date Analyzed: 8/9/06 Method Blank: MB-10565 Analytes **CAS Number** Result LQL Units 7440-38-2 6.0 Arsenic 3.9 mg/Kg Lead 7439-92-1 130 5.7 mg/Kg

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

* - Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 8/10/06